



P&S DETAIL PRODUCTS · WASH & PREP

FROSTBITE

SURFACE CLEANSE SNOW FOAM

SKU

F4032

32 OZ.

1 GALLON

F4001

Snow foam surface cleanse for pre-wash foaming (manufacturer product page). SDS provided as manufacturer draft US EN document on the P&S SDS index.

PERFORMANCE

ROLE	Snow foam surface cleanse for pre-wash foaming (manufacturer product page)
BRAND	P&S Detail Products
PH	9.5 (SDS)

APPLICATION & PHYSICAL

MDSC SIZES	32 oz. · 1 Gallon
TRANSPORT	Not regulated for transport
DOCUMENT	Manufacturer SDS

OVERVIEW

P&S Frostbite — Surface Cleanse Snow Foam. Manufacturer SDS pH 9.5. GHS signal: Warning. Catalog used only for name, SKU, image, and pack sizes.

DIRECTIONS

- 1 Dilute Frostbite into a foam cannon/lance per bottle guidance.
- 2 Apply thick foam bottom-to-top; allow to dwell while foam remains wet.
- 3 Rinse thoroughly from the top down.
- 4 Follow with a contact wash as needed.
- 5 Consult SDS for eye/skin hazard statements.

SAFETY SNAPSHOT

WARNING

Skin/eye irritation and related statements on manufacturer Frostbite SDS (draft index file)

APPEARANCE	See SDS
PH / DENS.	9.5 · —
FLASH POINT	See SDS
TRANSPORT	Not regulated for transport

Manufacturer SDS — P&S Frostbite →

SOURCES

1. Manufacturer product page — <https://psdetailproducts.com/products/frostbite-surface-clesnse-snow-foam-quart>
2. Manufacturer SDS (P&S Frostbite) — https://cdn.shopify.com/s/files/1/0317/0631/6932/files/Frostbite_Snow_Foam_US_EN_v1.0_DRAFT.pdf
3. Manufacturer SDS index — <https://psdetailproducts.com/pages/sds>
4. MDSC catalog for name / SKU / image / pack sizes only — <https://marinedetailsupply.com/products/p-s-frostbite-surface-cleanse-snow-foam>