



STARKE YACHT CARE · COMPOUNDS & POLISHES

STARKE TRIPLE P

CERAMIC PREP POLISH

SKU

TRP16

16 OZ

STEP 3 FINISH

TRP32

32 OZ

TRP128

128 OZ

Step 3 Finish in the Surface Restore System. Swirl remover with SiO₂ silica resin that primes gel coat for Starke ceramics and polymer sealants.

PERFORMANCE

ROLE	Step 3 Finish — ceramic-coating prep polish
FORMULA	Water-based oil-in-water emulsion; micro-abrasive + silica resin
DOES	Removes swirls / light scratches; deposits silica primer film
COATINGS	Engineered for Repel Pro and Liquid Thor (same silica backbone)
ALSO	Follow-up details on already-coated boats; polymer sealants

APPLICATION

MACHINE	Dual action or force rotation
PAD	Money Pad (\$) or soft foam
PREFERRED	Polish, then IPA wipe before coating (7-year field protocol)
ALT DWELL	If not IPA-wiping: 30–60 min before coating; do not solvent-wipe
PREP FIRST	Surface Prep alcohol before Triple P when coating
SIZES	16 oz · 32 oz · 128 oz

OVERVIEW

Triple P is the Step 3 Finish ceramic-prep polish in the STARKE Surface Restore System. The outer phase refines light defects to a mirror; the inner phase lays down a silica resin primer that is the same core constituent as Starke ceramics, so Repel Pro and Liquid Thor can cross-link into it. Product copy says Money Pad or soft foam on a dual-action. After seven years of field testing, Starke's preferred protocol is Triple P then an IPA wipe before coating. Only skip the IPA wipe if you will coat within 30–60 minutes and need the primer film left intact.

DIRECTIONS

- 1 Correct first (Level R / Blaze / Elevate as needed). Wash and IPA / Surface Prep so the panel is oil-free before Triple P.
- 2 DA or force rotation with a Money Pad or soft foam. Work until the polish refines to a light haze; wipe with a clean microfiber.
- 3 Preferred (all conditions): IPA wipe after Triple P, then apply Repel Pro, Liquid Thor, or the Starke sealant of choice.
- 4 If you must keep the primer film and will coat within 30–60 minutes, skip the IPA wipe — solvent would strip the silica resin.
- 5 Do not use Triple P if you cannot coat over it in a reasonable window. Annual coating maintenance: Venom wash, quick Triple P, re-topcoat.

SAFETY SNAPSHOT

CAUTION

SDS not published — treat as chemical product; follow label PPE.

APPEARANCE	Water-based emulsion polish
CHEMISTRY	Micro-abrasive + silica resin
SDS	Not published on Starke product page

Product page / SDS request → SDS not published on site

SOURCES

1. Starke product page — <https://starkeyachtcare.com/products/reel-shine-starke-triple-p-ceramic-prep-polish>
2. Starke Triple P how-to — <https://starkeyachtcare.com/blogs/news/what-exactly-is-triple-p-and-how-do-you-properly-use-it>
3. Starke Surface Restore process — <https://starkeyachtcare.com/blogs/news/how-to-restore-oxidized-gelcoat-on-a-boat-step-by-step-professional-process>